



Incident report - Gästrikke Rescue

Refers to Fire and rescue-operation report no. 2012A01701
This is an excerpt from a full report

Accident Sequence of events after arrival,

20:59 No one injured in place at the arrival

21:03 smoke-filled apartment floor plan, firemen inside, firemen on level 2

21:18 Run high pressure fan, firemen inside on level 2, no risk according to chief

22:28 5 persons transported to hospital

22:28 Local Rescue takes over

When I arrived on the scene, the tenants were outside the building. I was told that none were left in the apartments. I brought the DSPA 5, when I went through the stairwell, I peeked a little through the apartment's door and decided that I could not go into the apartment where the fire was. I have received information that about 1 meter further in the hall, you would have the kitchen directly to the right. I closed the apartment door, pulled the pin, opened the door again and threw the grenade into the kitchen. In the meantime, the other firefighters were ready to attack the fire from the inside, but I said we needed to wait a few minutes, so that the DSPA 5 could make its effect. Meanwhile I went around to the back of the house to see if I could see any fire from there, it was dark in the apartment but I thought that I could imagine a fire in the middle of the kitchen. Then I told the smoke divers to go in. They entered the apartment and put out the remaining hotspots, they also opened the patio door, they came back out to the staircase and we prepared a high pressure fan. Firefighters went back in and tore down the rests of the exhaust hood above the stove and extinguished a few small areas with water.

Conclusions:

- My conclusion is that we used a minimal amount of water and that the smoke divers had a good and safe working environment.
- My conclusion is that the DSPA 5 was very effective and a great help.

Weather

Wind speed: 1 m / s

Temperature: -2 ° C

Conditions: Fair

Evaluation - Improvement Proposal

Measures to prevent similar accidents: One should not leave the stove on after cooking

Brand i byggnad

Startutrymme:

- Kök

Bedömningen är: Säkerställd

Tot ant vån ovan mark: 2 st

Startvåning: 1

Startutrymmet låg i en överbyggd gård/galleria:

Startföremål:

- Annat
- Precisera
Frityrolja

Bedömningen är: Säkerställd

Fabrikat:

Typ:

Serienummer:



Incident report - Gästrikke Rescue

Refers to Fire and rescue-operation report no. 2012A01701
This is an excerpt from a full report

